

YAMAHA YZF-R3 / MT-03 EEC SLIP-ON R-11 SINGLE EXIT

Be sure to read the instruction carefully before starting the work. It is necessary to follow the contents to install Yoshimura product.

Product information



CAUTION Before beginning installation, let motorcycle cool down.

CAUTION Be sure not to damage each part during installation.

CAUTION Torque specification must be followed. If neglected, it may cause bolt and nut to fall off and damage to Yoshimura product and motorcycle.

CAUTION Metal Magic sleeve is coated with heat-resistant paint. Handle with care not to be hit or scratched by surroundings as the coating may come off. When cleaning silencer, use soft cloth with dish soap but do not use metal polish or chemical cleaner.

CAUTION Titanium Blue sleeve is colored by anodizing. Handle with care as the color may change. When cleaning silencer, use soft cloth with dish soap but do not use metal polish or chemical cleaner.

1. Product Information:

Description	YAMAHA YZF-R3 / MT-03 EEC Slip-On R-11 Single Exit	Cyclone Type	Y346S11C1
Part Number	Stainless Sleeve (SSC) : 1A0-346-5E50	Main Material	Stainless steel
	Metal Magic Sleeve (SMC) : 1A0-346-5E20	EEC Approval No.	e3 1172⑨
	Titanium Sleeve (STC) : 1A0-346-5E80	Weight [STD : 2.8kg]	(SSC) & (SMC) : 2.1kg
	Titanium Blue Sleeve (STBC) : 1A0-346-5E80B		(STC) & (STBC) : 1.9kg

2. Applicable Model :

Model	YZF-R3 / MT-03
-------	----------------

3. Contents:

No.	Descriptions	Part No.	Q'ty	No.	Descriptions	Part No.	Q'ty
1	Tailpipe	185-346-5E00	1	5	Button Bolt M6x25	803-206-4025	2
2	Silencer Assy Stainless Sleeve	1A6-346-5E50	1	6	Washer M6	812-106-0000	2
	Silencer Assy Metal Magic Sleeve	1A6-346-5E20		7	Flange Nut M6	823-006-1000	2
	Silencer Assy Titanium Sleeve	1A6-346-5E80		8	Spacer 6-13-4	860-006-1304	2
	Silencer Assy Titanium Blue Sleeve	1A6-346-5E80B		9	Exhaust Spring	118-001-0000	2
3	Silencer Bracket	161-346-0200	1	10	Gasket #346	129-346-3000	1
4	Heat Guard	161-346-0000	1				

Parts Diagram

SD#70 (Pre-installed)
Part No : 138-138-3870

CAUTION
Without SD#70, the EEC Approval is not valid.

